

## **Appendix D**

### **Site Inspection Forms, Radiological Survey Information, and Photographs of Operable Units 2-13 and 2-14 Sites (2002)**



## **Appendix D**

### **Site Inspection Forms, Radiological Survey Information, and Photographs of Operable Units 2-13 and 2-14 Sites (2002)**

Appendix D contains site inspection forms, radiological survey information, and color photographs of the 15 Comprehensive Environmental Response, Compensation, and Liability Act sites at Operable Units 2-13 and 2-14 in Waste Area Group 2. These photographs were taken during the most recent institutional control inspection in June 2002, and they depict the current physical condition of each site in Operable Units 2-13 and 2-14.




Figure D-1. The TRA-03 Warm Waste Pond cover looking east (PN02274-1)




Figure D-2. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA-03 Warm Waste Pond cover (PN02274-1-15).



Figure D-3. Rabbitbrush growing on western portion of TRA-03 Warm Waste Pond cover (PN02274-1-16).






Figure D-4. West side of TRA-06 Chemical Waste Pond looking east (PN02274-1-6).




Figure D-5. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA-06 Chemical Leach Pond cover (PN02274-1-7).





Figure D-6. View of TRA-06 Chemical Leach Pond cover looking north (PN02274-1-8).